

# HYTORC

## TOOL MODEL: VERSA-2 W / HEX LINK (LINK SIZES #1-#7)

### PRESSURE/TORQUE CONVERSION CHART

#### Standard Torque Chart

PRESSURE IN PSI	TORQUE IN			PRESSURE IN BAR
	FT. LBS.	KGM	NM	
1500	261	36	354	104
1600	279	39	378	110
1800	314	43	426	124
2000	349	48	473	138
2200	384	53	521	152
2400	419	58	568	165
2600	454	63	615	179
2800	489	68	663	193
3000	524	72	710	207
3200	559	77	758	220
3400	594	82	805	234
3600	629	87	852	248
3800	663	92	899	262
4000	698	97	947	276
4200	735	102	996	290
4400	771	107	1045	303
4600	807	112	1095	317
4800	844	117	1144	331
5000	880	122	1193	345
5200	916	127	1242	358
5400	952	132	1290	372
5600	988	137	1339	386
5800	1024	142	1388	400
6000	1060	147	1436	414
6200	1094	151	1483	427
6400	1128	156	1530	441
6600	1163	161	1576	455
6800	1197	166	1623	468
7000	1232	170	1669	482
7200	1269	175	1720	496
7400	1306	181	1771	510
7600	1344	186	1821	524
7800	1381	191	1872	538
8000	1418	196	1923	552
8200	1455	201	1972	565
8400	1491	206	2021	579
8600	1527	211	2071	593
8800	1564	216	2120	607
9000	1600	221	2169	620
9200	1636	226	2218	634
9400	1672	231	2267	648
9600	1708	236	2315	662
9800	1744	241	2364	676
10000	1780	246	2413	690